<u>R-SE Ridge Front Bumper Bull Bar Light Kit</u>
1 - LED Light
1 - Push Switch
1 - Fuse - 20Amp
1 - Fuse holder
2 - Ring Terminals
3 - Butt Connectors
2 - Spade Female Connectors
2 – 12ft of Wire different colors

⚐ If any parts are missing or damaged please call 435-752-4580 prior to Light Kit install.

Step 1. Feed supplied white wire up through the Bull Bar and out the small rear hole. Use a butt connector to connect the white wire of the LED to the white wire you fed through. (Example 1.)

Example 1.

Example 2.

Step 2. Feed supplied black wire up through Bull Bar and out the bigger front hole. Pull the black LED wire out the top hole as well. Attach female connectors to both black wires. (Example 2.)

Step 3. Plug female plugs on black wires into each side of the switch. (Example 3.)

Example 3.

Step 4. Push the LED into the hole until it snaps in. Do the same with the switch.

Step 5. Route the black wire up to the battery. Keep the wire away from any moving parts. Butt connect the black wire and the fuze box together. Use the white wire to ground to the chassis or engine via one ring terminal. Use the other ring terminal to connect the fuze box to the positive side of the battery. (Example 4.)

Example 4.