

# **YOSHIMURA**

RESEARCH&DEVELOPMENT OF AMERICA, INC.

5420 DANIELS STREET STE A, CHINO CA 91710 · (800)634-9166 · (909)628-4722 · FACSIMILE (909)591-2198

\*\*WWW.YOSHIMURA-RD.COM\*\*

# OFF-ROAD PERFORMANCE EXHAUST SYSTEM Spark Arrested

2010-2013 Suzuki RMZ-250

2183514

STAINLESS STEEL FULL-SYSTEM RS4 WITH ALUMINUM SLEEVE



THIS PRODUCT IS DESIGNED FOR USE IN CLOSED COURSE RACING AND IS NOT INTENDED FOR ANY OTHER USE.



**%** 

CAUTION: The muffler packing on this system MUST be replaced every 6-8 hours of use, or after each moto. Failure to follow recommended muffler re-packing interval can cause muffler damage and may void the warranty.



NOTE: IN THE STATE OF CALIFORNIA, IT IS ILLEGAL TO MODIFY THE EMISSION CONTROL SYSTEM INCLUDING THE CARBURETORS OR FUEL INJECTION OF ANY HIGHWAY VEHICLE.

Caution: Exhaust system may be extremely hot. Let motorcycle cool

down before beginning installation.

Note: Read through all instructions before beginning installation.

#### Tools Needed:

Metric Socket Set Ratchet Wrench and Extension Torque Wrench Spring Puller Tool Hex Key Set

### Installation Steps:

- 1 Stock Exhaust Removal
  - a. Remove right rear number plate (see Fig. 1 for fastener locations).
  - b. Loosen stock muffler clamp.
  - c. Unbolt chassis and muffler mount bolts.
  - d. Remove stock muffler (see Fig. 2 for fastener locations).
  - e. Remove stock header heatshield from header.
  - f. Remove stock header (see Fig 3 for fastener locations).

    Note: Inspect stock header gasket for damage. If damaged, replace with new stock gasket, PN: 14181-49H00.

#### 2 Install Yoshimura Exhaust

- a. Install Yoshimura header using stock nuts. Leave loose.
- b. Temporarily remove tailpipe-to-muffler spring.
- c. Install supplied rubber grommet into aluminum muffler mounting bracket. Install aluminum insert into rubber grommet (make sure shoulder of aluminum insert faces toward the frame, see Fig. 4).
- d. Install Yoshimura tailpipe and muffler onto Yoshimura header.
- e. Mount stock chassis mount bolt to tailpipe. Leave loose.
- f. Mount muffler with stock muffler mount bolt and washer. Leave loose.
- g. Install supplied tailpipe-to-muffler spring.
- h. Check exhaust for proper position and clearance and adjust if necessary.
- I. Tighten stock header nuts to 15 ft-lb (21 N-m).
- j. Tighten chassis mount and muffler mount bolts to 15 ft-lb (21 N-m).
- k. Install stock header heatshield on Yoshimura header using stock heatshield bolts. Tighten to 7 ft-lbs ( 10 N-m ).



Fig. 1




Fig. 2




Fig. 3

#### 3 Reinstall

a. Reinstall number plate.

b. It is recommended that the muffler and tailpipe be wiped down with rubbing alcohol to remove oil and fingerprints. This will help prevent tarnishing of the finish after the exhaust is heated up.

Before starting motorcycle, check for proper clearance between new exhaust system and rear suspension (i.e. tire, swingarm, brake, rear shock, etc). If any problem is found, please carefully follow through the installation steps again. If problem still persists, please call Yoshimura tech department at (800) 634-9166 / in CA (909) 628-4722.

NOTE: After starting motorcycle, it is normal for new exhaust system and muffler to emit smoke until oil residue burns off.





Fig. 4

## Part List: Page 4

### PN: 2183514




NO.	DESCRIPTION	QTY	PART #		
1	Yoshimura Stainless Steel Header	1	2183-101		
2	Yoshimura Tailpipe	1	2183-144		
3	Yoshimura Race Muffler with Aluminum Sleeve	1	2183514-RMA		
4	Short Exhaust Spring	2	RACE-SPX-1		
5	Muffler Mount Rubber Grommet	1	Z1022		
6	Aluminum Insert	1	ALS-010		
**	Instructions Manual	1	INST KIT		
**	Spring Puller Tool	1	ST-200		
**	Yoshimura Vinyl Sticker	1	17029		
**	Muffler Wash Plug	1	347PLUG		
OPTIONAL REPLACEMENT PARTS					
RS4 Sound Insert		INS-14-K			
2m-MAX Sound Insert		INS-14-K			
Spark Arrestor		SA-04-K			
Re-pack Kit		REPACK-RS4-PK11			



# **YOSHIMURA**

RESEARCH&DEVELOPMENT OF AMERICA, INC.

#### SA-04-K YOSHIMURA TEC-SD10 SPARK ARRESTOR KIT



NO.	DESCRIPTION	QTY	PART #
1	6mm X 12mm Button Head Cap Screw	1	M6X12BHS
2	RS4 Spark Arrestor Ring 1.500"	1	RS4-RING-1500
3	TEC-SD10 Spark Arrestor	1	TEC-SD10
4	Yoshimura Exhaust	**	**

- 1 Using a 4mm Allen key, remove the bolt that secures the aluminum ring and spark arrester to the muffler (see Parts Diagram for location).
- 2 Remove the spark arrester from the muffler.
- 3 Using a wire brush, remove carbon deposits from spark arrester screen. Inspect the screen for excessive wear or damage. If spark arrester is excessively worn or damaged, the spark arrester must be replaced. Cleaning and inspection should be performed after every 60 hours of use.

CAUTION: Gloves and safety glasses should be worn while cleaning spark arrester.

4 Re-install spark arrester and aluminum ring. Torque the spark arrester securing bolt to 1.0 kg-m (7.3 lb-ft). NOTE: It is recommended that a low strength "Loc-tite" is used on the spark arrester securing bolt.